



Textiles and Apparel Solutions Centre,
The Warehouse, Brewery Lane,
Leigh, Lancashire, WN7 2RJ, UK
Telephone: +44 (0) 1942 265700
Facsimile: +44 (0) 1942 670 788
www.intertek.com/consumergoods

BS EN 14465:2003 Test Report

Report Ref: LEHTX00910122	Buying Division: NONE GIVEN
Date Received: 21/09/2016	Date Issued: 23/09/2016

Company Name & Address	CAMIRA FABRICS LIMITED MELTHAM MILLS MELTHAM WEST YORKSHIRE HD9 4AY
Contact Name	REBECCA GRIMES

Order No.:	58056
Description:	NONE GIVEN
Colour(s):	BEEZON
Supplier:	NONE GIVEN
End Use:	UPHOLSTERY
Quoted Composition:	NONE GIVEN
Ref/Style/Stroke No.:	CALL 4885
Quality:	KENDAL
Batch No.:	NONE GIVEN
Spec. No.:	TABLE 1

Test	Method	Colour	Pass/Fail
ABRASION RESISTANCE (FLAT WOVEN)	BS EN ISO 12947-2/BS EN 14465: 2003 ANNEX A		Pass A

Samantha Davey
(Technician)



Upholstery - Martindale Abrasion (12 kPa Load)		RH 65% +/-4% / Temp 20°C +/-2°C			
Sample	Results				Minimum Requirements
	Change in Shade @ 3,000 Revs = Grade 4				A = 35,000 revs B = 12,000 / 30,000 revs C = 4,000 / 10,000 revs
Fabric Type Flat Woven	Heads 2,3 & 4 No fabric breakdown @ 35,000 revs Note: The sample was stopped every 1000 revs, cooled for 10 minutes & with every pill removed @ 1000 intervals at the customers request				
Overall Result	35,000 revs				
Overall Performance Level	A				
BS 2543: 2004 Classification (Minimum levels for customer reference)					
	LD	GD	HD	GC	SC
Flat Woven	B - 15,000	B - 20,000	B - 25,000	B - 30,000	A - 40,000
Figured Weaves	B - 12,000	B - 15,000	B - 20,000	B - 30,000	A - 40,000
Woven/Flocked/Non-Woven Pile Fabrics	C - 15,000	C - 20,000	B - 25,000	B - 25,000	B - 30,000
Knitted	B - 15,000	B - 20,000	B - 25,000	B - 25,000	B - 30,000



Textiles and Apparel Solutions Centre,
The Warehouse, Brewery Lane,
Leigh, Lancashire, WN7 2RJ, UK
Telephone: +44 (0) 1942 265700
Facsimile: +44 (0) 1942 670 788
www.intertek.com/consumergoods

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

